






A Ø6*30 X6	B X2	C ST4*30 X6	D X6	E ST4*10 X6	F X2	G X2	H ST4*12 X8	
I X8	J X2	K X4	L ST4*12 X4	M X4	N ST4*16 X8	O X2	P X4	
Q X2	R X1	S X2	T X4					






9





10






7




1




8




2





3



5



4



6